


MARK T. PORTER
Superintendent of Schools



Members of the Board

District # 1
BOBBY HIGHSMITH
Chairman

District # 2
ANDY GRIFFITHS

District # 3
MINDY CONN
Vice-Chairman

District # 4
JOHN R. DICK

District # 5
RONALD A. MARTIN

Bid No: ITB 2019904

Name of Bid: Founders Park Infield Improvements

Post Date: 10/17/18

Notice Post Time: 4:15 PM

Q&A No.3

1. How deep is the clay for the warning track area? **ANSWER – Unknown, warning track area depth should remain the approximate depth it is now. Vendor may visit site to take measurements if needed.**
2. What is the PSI and gallons per minute for the irrigation? **ANSWER – Unknown, the irrigation system is open and available for inspection daily. You may contact us and request a specific time and we will run the system for inspection.**
3. How deep is the tilling? **ANSWER – Till between 3" and 4", but not deeper than existing clay. Do not bring up non clay materials.**
4. How to deep to hull out areas to be grassed? **ANSWER – This will vary based on your grading needs. See Addendum No.2 for information about alternate pricing of replacement of the root zone materials.**
5. Will there be a change order for any additional irrigation heads that will need to be replaced? **ANSWER – No, please see section 3.d. (page 7) of original bid document.**
6. Will the silica sand be used for topdressing for the clay and grassing area? **ANSWER – The silica sand is intended for top dressing the new sod areas to fill gaps and seams.**